



LEGEND

- EXISTING PROPERTY LINE
- - - PROPOSED PROPERTY LINE
- EXISTING CONTOURS
- - - PROPOSED CONTOURS
- X 140.5 SPOT ELEVATIONS
- EASEMENT
- ▭ EXISTING DRAIN INLET (CATCH BASIN)
- ▭ CATCH BASIN
- STORM PROPOSED STORM LINE
- EXISTING UTILITY POLE
- EXISTING HYDRANT
- EXISTING WATER LINE
- PROPOSED WATER LINE
- PROPOSED SEWER LINE
- SETBACK LINE
- ▭ RETAINING WALL
- SILT FENCE
- LIMIT OF DISTURBANCE
- ▨ STABILIZED CONSTRUCTION ENTRANCE
- EXISTING TREE
- MH EXISTING MAINHOLE
- PROPOSED MAINHOLE




Figure 5-3: Mature Trees
Butterfield
 Village of Cold Spring, Putnam County, NY
 Source: DCAK-MSA, Existing Conditions Site Plan, Rev. 01/27/12
 Scale: 1" = 80'

UNAUTHORIZED ALTERATION OR ADDITION TO THIS PLAN BEARING A LICENSED PROFESSIONAL'S SEAL IS A VIOLATION OF SECTION 7209, SUB-DIVISION 2, OF THE NEW YORK STATE EDUCATION LAW.
 ONLY COPIES FROM THE ORIGINAL OF THIS PLAN MARKED WITH AN ORIGINAL PROFESSIONAL'S SEAL SHALL BE CONSIDERED VALID TRUE COPIES.

Tim Miller Associates, Inc., 10 North Street, Cold Spring, New York 10516 (845) 265-4400 Fax (845) 265-4418